

The diagram illustrates the sequence of weighing steps using three digital scales. Each scale has a downward arrow to its left, indicating the order of use. The scales display the following units: kg, st/lb, and lb.





Diagram illustrating the scale's display and foot placement. The scale has a digital display showing "00 kg". The text "Auto On" is visible. A foot is shown stepping onto the scale platform, with an arrow indicating the "CENTER" position. A circular dial on the right side of the scale shows the number "3".












Diagram illustrating a nested loop structure. A large rectangle contains a smaller rectangle. Inside the large rectangle is a box labeled "Lo". Inside the smaller rectangle is a box labeled "Lo".



CE

